


# KEW Report Installation Manual



This manual contains instructions how to install the special software "KEW Report" supplied with KEW6205, MODEL8212USB and 8212-RS232C.

## 1. Introduction

- **Interface**  
This instrument is equipped with a USB interface. Communication method: USB Ver1.1  
The internal data of the instrument can be transferred to a PC via USB communication.
- **System Requirements**
  - OS (Operation System)  
For the supported OS, check the label on the CD case or visit our website.
  - Display  
1024×768 dots, 65536 colors or more
  - HDD (Hard-disk space required)  
100 Mbyte or more
- **Trademark**
  - Windows® is a registered trademark of Microsoft in the United States.

The latest software is available for download from our website.  
www.kew-ltd.co.jp



- (7) Click **Finish** when "InstallShield Wizard Complete" dialog box appears. When the installation wizard completes, subsequent installation begins automatically. Please refer to **3. USB driver installation**.



**How to un-install "KEW Report" :**  
Open the Control panel, click **Add/ Remove Programs** and select "KEW Report" .


## 2. Installation of "KEW Report"

**(For Windows 7)**

- (1) Always check the followings before installing "KEW Report" .
  - To prepare your system for installation, please close all open programs.
  - Be sure NOT to connect the instrument to a PC until the installation completes.
  - Installation shall be done with Administrator right.
- (2) Insert the supplied CD-ROM containing "KEW Report" in your PC' s CD-ROM drive. Click **Run install.exe** when AutoPlay window pops up.

If the installer does not run automatically, click the CD icon to run the "install.exe" file. If the User Account Control dialog box appears, click **Yes**.

- (3) Read through and understand the License Agreement and click " I accept..." , and then click **Next**.




- (4) Click **Next** after entering the user information and other supplementary information.

- (5) Confirm the information on installation, and then click **Install** to start the installation process.

If a message requiring restarting your computer is displayed, click **Yes** and restart your computer. Installation process will then restart.

Restarting your computer is essential to install the application properly.

- (6) Click **Finish** when "InstallShield Wizard Complete" dialog box appears. When the installation wizard completes, subsequent installation begins automatically. Please refer to **3. USB driver installation**.



**How to un-install "KEW Report" :**  
Open the Control panel, click **Add/ Remove Programs** and select "KEW Report" .

## 3. USB Driver Installation

**(For Windows 7)**


- (1) When KEW Report has been successfully installed in your computer, the following dialog box appears to start installing the USB driver. Click **Next**.




- (2) Read through and understand the End User License Agreement and click " I accept..." , and then click **Next**.



- (3) If the following Security Warning message appears, click **Install**.



- \* If the following Security Warning message appears, click on the "Install this driver anyway" . (It is no problem to continue installing because operation has already been verified.)



**(For Windows 8 / 10)**

- (1) Always check the followings before installing "KEW Report" .
  - To prepare your system for installation, please close all open programs.
  - Be sure NOT to connect the instrument to a PC until the installation completes.
  - Installation shall be done with Administrator right.

- (2) Insert the supplied CD-ROM containing "KEW Report" in your PC' s CD-ROM drive. Then the following pop-up will appear at the upper right on the screen. Left-click on this box.

DVD RW Drive (E:) KEWReportV2.60  
Tap to choose what happens with this disc.

- (3) Click **Run install.exe** when the box as shown below appears. If User Account Control dialog box appears, click **Yes**.



- If neither (2) nor (3) appears, click the CD icon and run "install.exe" file.

- (4) Installation completes when the following window appears. Click **Finish**.




The USB driver has been successfully installed.

**To restart the interrupted USB driver installation process, right click on the CD drive and click Open. Click and start "kewusbserial200\_setup.exe" in the DRIVER folder.**

**How to un-install the USB driver:**  
Open the Control panel, click **Add/ Remove Programs** and select "**Windows Driver Package - KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD. KYORITSU USB Driver Package-Bus**" .

- (4) Read through and understand the License Agreement and click " I accept..." , and then click **Next**.



- (5) Click **Next** after entering the user information and other supplementary information, and click **Next**.

- (6) Confirm the information on installation, and then click **Install** to start installation.

**(For Windows 8 / 10)**

- (1) When KEW Report has been successfully installed in your computer, the following dialog box appears to start installing the USB driver. Click **Next**.



- (2) Read through and understand the End User License Agreement and click " I accept..." , and then click **Next**.




(3) If the following Security Warning message appears, click **Install**.



If the following Warning message appears, click "Install this driver software anyway". (It is no problem to continue installing because operation has already been verified.)



(2) Click **Ports (COM & LPT)** to see the COM port number assigned for the instrument.



(3) If the assigned number is out of COM1 to COM32, follow the instructions described in **5. Changing COM Port No.** and change the number accordingly.

(4) Installation completes when the following window appears. Click **Finish**.



The USB driver has been successfully installed.


**To restart the interrupted USB driver installation process, right click on the CD drive and click Open. Click and start "kewusbserial200\_setup.exe" in the DRIVER folder.**

**How to un-install the USB driver:**  
Open the Control panel, click **Add/ Remove Programs** and select "**Windows Driver Package - KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD. KYORITSU USB Driver Package-Bus**".


#### 4. Checking COM Port No.

(For Windows 7)


(1) Click **Start** and then **Devices and Printers**.



(2) Right-click on the instrument icon and click **Properties**.




(3) Click the **Hardware** tab to see the COM port number assigned for the instrument.



(4) If the assigned number is out of COM1 to COM32, follow the instructions described in **5. Changing COM Port No.** and change the number accordingly.

(For Windows 8 / 10)

(1) Right-click **Start** button and then **Device Manager**.



#### 5. Changing COM Port No.


(For Windows 7/ 8/ 10)

(1) Follow the procedures described in **4. Checking COM Port No.** and perform steps (1) to (3).


(2) After performing step (3), select the displayed instrument name (**COMx**) and click **Properties**.




(3) Click **Port Settings** tab, and then click **Advanced...**



\*If **Advanced...** is gray and you cannot open it: Click **General** tab and then **Change settings**.



(4) Click and select a number (from COM1 to COM32) on the **COM Port Number:** box, and then click **OK**.



#### 6. Starting KEW Report

Start "KEW Report" by; 1) clicking the icon for "KEW Report" on your desktop, or 2) clicking **Start -> Program -> KEW -> KEW Report**.


(1) COM Port setting

Click **Communication -> COM Port** on the Main Window of "KEW Report", and select the pre-set COM Port number.



(2) Download

Click **Communication -> Download** on the Main Window of "KEW Report". Then the following window appears. Click **Exit** or "x" box at the upper right of the window to close the program.



Further detailed information is given in the **HELP**.



**KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD.**  
2-5-20, Nakane, Meguro-ku, Tokyo, 152-0031 Japan  
Phone: +81-3-3723-0131  
Fax: +81-3-3723-0152  
Factory: Ehime, Japan  
[www.kew-ltd.co.jp](http://www.kew-ltd.co.jp)